

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

FIG. 1



**FIG. 2**




FIG. 3(a)




FIG. 3(b)




FIG. 4




FIG. 5(a)





FIG. 5(b)



Technical drawing of a mechanical assembly in cross-section. The main housing (3) contains internal components including a central shaft (14) with a flange (22), a bearing (15), and a seal (17). A bolt (5) and nut (21) are used for clamping. A separate component (9) is shown on the left, connected to the housing via a flange (4). The assembly is labeled C1, C2, and C3.

FIG. 8






FIG. 9




FIG. 10




FIG. 11(a)




FIG. 11(b)





FIG. 12






FIG. 13

